

Filled out by: G.J.DEMERS

Date: 09 / 28 / 2011

Switch Inspection Form

Railroad: WACR CRL B/S	Town: NEWBURY
Valuation Sheet: V 43 / 41	Valuation Stationing: 2134 + 40
Mile Post: D 0.48	GPS Coordinates: N: 44 09.162 W: 72 02.638

Switch Name: SOUTH WYE

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 112 RE Condition Good Fair Poor

Turnout Type # 8 Right Hand Left Hand Equilateral

Switch Point Length 15 FT 0 IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 14 FT 7 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



