

Filled out by: G.J.DEMERS

Date: 08 / 24 / 2011

### Switch Inspection Form

Railroad: <b>WACR CRL B/S</b>	Town: <b>FAIRLEE</b>
Valuation Sheet: <b>V 43 / 19</b>	Valuation Stationing: <b>990 + 84</b>
Mile Post: <b>D 22.22</b>	GPS Coordinates: N: <b>43 52.489</b> W: <b>72 10.639</b>

Switch Name: NORTH ELY

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 112 RE Condition  Good  Fair  Poor

Turnout Type # 9  Right Hand  Left Hand  Equilateral

Switch Point Length 16 FT 6 IN Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 16 FT 0 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signaled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_





