

Filled out by: G.J.DEMERS

Date: 08 / 24 / 2011

Switch Inspection Form

Railroad: WACR CRL B/S	Town: FAIRLEE
Valuation Sheet: V 43 / 19	Valuation Stationing: 984 + 05
Mile Post: D 22.34	GPS Coordinates: N: 43 59.392 W: 72 10.708

Switch Name: NORTH X-OVER

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 112 RE Condition Good Fair Poor

Turnout Type # 10 Right Hand Left Hand Equilateral

Switch Point Length 16 FT 6 IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 16 FT 6 IN Condition Good Fair Poor ^{CRACKED}

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



