

Filled out by: G.J.DEMERS

Date: 08 / 24 / 2011

### Switch Inspection Form

Railroad: <b>WACR CRL B/S</b>	Town: <b>FAIRLEE</b>
Valuation Sheet: <b>V 43 /</b>	Valuation Stationing: <b>940 + 37.9</b>
Mile Post: <b>D 23.17</b>	GPS Coordinates: N: 43      51.757 W: 72      11.172

Switch Name: SOUTH ELY

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 112RE Condition  Good  Fair  Poor

Turnout Type # 10  Right Hand  Left Hand  Equilateral

Switch Point Length 15 FT 0 IN Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 16 FT 4 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signaled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_







