

Filled out by: G.J.DEMERS

Date: 08/09/2011

Switch Inspection Form

Railroad: WACR CRL L/S	Town: SUTTON
Valuation Sheet: V 43 / 84	Valuation Stationing: 4414 + 58
Mile Post: L 20.60	GPS Coordinates: N: 44 41.702 W: 72 04.607

Switch Name: NORTH WILKINSON SWITCH

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 100 REHF Condition Good Fair Poor

Turnout Type # 13 Right Hand Left Hand Equilateral

Switch Point Length 22 FT 0 IN Tie Condition Good Fair Poor

Frog Type Rigid Solid Manganese Spring Other _____

Frog Length 20 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signalled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



