

Filled out by: G.J.DEMERS

Date: 08 / 09 / 2011

### Switch Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>SUTTON</b>
Valuation Sheet: <b>V 43 / 83</b>	Valuation Stationing: <b>4353 + 42</b>
Mile Post: <b>L 21.74</b>	GPS Coordinates: N: <b>44 41.328</b> W: <b>72 03.322</b>

Switch Name: SOUTH WINDSOR SWITCH

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 100 REHF Condition  Good  Fair  Poor

Turnout Type #11  Right Hand  Left Hand  Equilateral

Switch Point Length 22 FT 0 IN Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 20 FT 0 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signalled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_



