

Filled out by: G.J.DEMERS

Date: 06 / 15 / 2011

### Switch Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BURKE</b>
Valuation Sheet: <b>V 43 / 78</b>	Valuation Stationing: <b>4092 + 32</b>
Mile Post: <b>L 26.76</b>	GPS Coordinates: N: <b>44 38.440</b> W: <b>71 59.152</b>

Switch Name: SOUTH SWITCH

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 100 REHF Condition  Good  Fair  Poor

Turnout Type # 11  Right Hand  Left Hand  Equilateral

Switch Point Length 22 FT 0 IN Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 17 FT 0 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signalled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_



