

Filled out by: G.J.DEMERS

Date: 06 / 16 / 2011

Switch Inspection Form

Railroad: WACR CRL L/S	Town: LYNDON
Valuation Sheet: V 43 /	Valuation Stationing: 3666 + 71
Mile Post: L 34.74	GPS Coordinates: N: 44 32.069 W: 72 00.135

Switch Name: SOUTH SWITCH

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 100 REHF Condition Good Fair Poor

Turnout Type # 9 Right Hand Left Hand Equilateral

Switch Point Length 16 FT 6 IN Tie Condition Good Fair Poor

Frog Type Rigid Solid Manganese Spring Other _____

Frog Length 16 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signalled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



