

Filled out by: G.J.DEMERS

Date: 08 / 23 / 2011

Switch Inspection Form

Railroad: WACR CRL L/S	Town: LYNDON
Valuation Sheet: V 43 / 68	Valuation Stationing: 3560 + 87
Mile Post: L 36.75	GPS Coordinates: N: 44 30.433 W: 71 59.631

Switch Name: NORTH CALKINS

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 100 REHF Condition Good Fair Poor

Turnout Type #9 Right Hand Left Hand Equilateral

Switch Point Length 16 FT 6 IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 15 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signalled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



