

Filled out by: G.J.DEMERS

Date: 08/11/2011

### Switch Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>St. JOHNSBURY</b>
Valuation Sheet: <b>V 43 / 61</b>	Valuation Stationing: <b>+</b>
Mile Post: <b>L .</b>	GPS Coordinates: N: <b>44 25 . 071</b> W: <b>72 00 . 889</b>

Switch Name: NORTH # 1

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 100 REHF Condition  Good  Fair  Poor

Turnout Type # 9  Right Hand  Left Hand  Equilateral

Switch Point Length 16 FT 6 IN Tie Condition  Good  Fair  Poor

Frog Type <sup>SELF GUARDED</sup>  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 16 FT 0 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other SELF GUARDED FROG

Signalled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_