

Filled out by: G.J.DEMERS

Date: 08 / 10 / 2011

### Switch Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BARNET</b>
Valuation Sheet: <b>V 43 / 52</b>	Valuation Stationing: <b>2698 + 42</b>
Mile Post: <b>L 53.09</b>	GPS Coordinates: <b>N: 44 17.642</b> <b>W: 72 02.925</b>

Switch Name: EAST TRACK SWITCH

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 100 REHF Condition  Good  Fair  Poor

Turnout Type # 11  Right Hand  Left Hand  Equilateral

Switch Point Length 22 FT 0 IN Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 17 FT 0 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signalled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_



