

Filled out by: G.J.DEMERS

Date: 08 / 09 / 2011

### Switch Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BARTON</b>
Valuation Sheet: <b>V 43 / 96</b>	Valuation Stationing: <b>5018 + 98</b>
Mile Post: <b>L 9.14</b>	GPS Coordinates: <b>N: 44 48.455</b> <b>W: 72 12.287</b>

Switch Name: COUTURE

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 100 REHF Condition  Good  Fair  Poor

Turnout Type \* 11  Right Hand  Left Hand  Equilateral

Switch Point Length 22 FT 0 IN Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 17 FT 0 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signalled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_



