

Filled out by: G.J.DEMERS

Date: 08 / 09 / 2011

Switch Inspection Form

Railroad: WACR CRL L/S	Town: BARTON
Valuation Sheet: V 43 / 92	Valuation Stationing: 5017 + 07
Mile Post: L 9.18	GPS Coordinates: N: 44 48.412 W: 72 12.324

Switch Name: MILL SWITCH

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 100 REHF Condition Good Fair Poor

Turnout Type _____ Right Hand Left Hand Equilateral

Switch Point Length _____ FT _____ IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length _____ FT _____ IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signalled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____