

Filled out by: G.J.DEMERS

Date: 08 / 09 / 2011

Switch Inspection Form

Railroad: WACR CRL L/S	Town: BARTON
Valuation Sheet: V 43 / 95	Valuation Stationing: 3012 + 85
Mile Post: L 9.27	GPS Coordinates: N: 44 48.368 W: 72 12.365

Switch Name: SOUTH SWITCH

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 100 REHF Condition Good Fair Poor

Turnout Type # 11 Right Hand Left Hand Equilateral

Switch Point Length 22 FT 0 IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 17 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signalled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



