

Filled out by: G.J.DEMERS

Date: 07/17/2014

Switch Inspection Form

Railroad: WACR MBL	Town: <u>BOZRE</u>
Valuation Sheet: PAGE 16 OF 18	Valuation Stationing: <u>575 + 82 (ON SIDING)</u>
Mile Post: <u>M 10.90</u> <u>(ON SIDING)</u>	GPS Coordinates: N: <u>44 10 12</u> W: <u>72 29 02</u>

Switch Name: # 3

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 80 Condition Good Fair Poor

Turnout Type # 7 Right Hand Left Hand Equilateral

Switch Point Length 15 FT 0 IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 16 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



