

Filled out by: G.J.DEMERS

Date: 06 / 02 / 2014

Switch Inspection Form

Railroad: WACR MBL	Town: MONTPELIER
Valuation Sheet: PAGE 7 OF 18	Valuation Stationing: 17 + 60
Mile Post: Y 0.33	GPS Coordinates: N: 44 14 36 W: 72 32 34

Switch Name: _____

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 85 Condition Good Fair Poor

Turnout Type #10 Right Hand Left Hand Equilateral

Switch Point Length 15 FT 0 IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 16 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other
(BROKEN HANDLE)

Guardrail Type Bolted rail cast Other SPIKED RAIL

Signaled Yes No Security Switch Lock Keeper MISSING

Number of Photos Taken 2

Remedial Action (if any) _____

58' W of Gausson Hill Com. Park X-ING



