



08/07/2020



08/07/2020



08/07/2020



08/07/2020

A photograph of a paved road with a yellow double line. The road surface is cracked, with a prominent vertical crack on the left and a diagonal crack crossing the yellow lines. A metal guardrail runs along the top edge of the road. A date stamp '08/07/2020' is visible in the bottom right corner.

08/07/2020



08/07/2020



08/07/2020







08/07/2020



08/07/2020



08/07/2020





08/07/2020



08/07/2020





08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020







08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020





08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020



08/07/2020







08/07/2020



08/07/2020



08/07/2020





08/07/2020



08/07/2020