



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020

A photograph of a cracked asphalt road surface. The road is dark grey with several prominent, irregular cracks running across it. A large, dark shadow is cast across the lower half of the road. In the background, a metal guardrail is visible, supported by wooden posts, with green foliage behind it. The date '07/16/2020' is printed in orange text at the bottom center of the image.

07/16/2020



07/16/2020



07/16/2020





07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020





07/16/2020





07/16/2020



07/16/2020



07/16/2020





07/16/2020



07/16/2020



07/16/2020





07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020



07/16/2020





07/16/2020