









HEAVY RUST AND CORROSION WITH SCATTERED  
PERFORATIONS AT THE OUTLET.





3234







