

5/10 4/107
1/16

APRIL 2008

A photograph showing a concrete structure, possibly a bridge or a dam, with a large, jagged crack running horizontally across the middle. The crack is deep and appears to be filled with dark material. To the right of the crack, there is a vertical concrete pillar. To the left, there is a dark, textured surface. The ground in the foreground is rough and uneven, with some loose concrete and debris. A person's foot, wearing a brown shoe, is visible in the bottom left corner. The water on the right side is dark and rippling. The text "APRIL 2008" is overlaid in red in the center. There are also some handwritten numbers in the top left corner: "5/10 4/107" and "1/16".