





A person wearing a bright orange safety vest over a dark shirt, blue jeans, and brown work boots is sitting on the metal guardrail. They are holding a small object, possibly a pen or a tool, in their hands.

The guardrail is made of galvanized steel and shows significant damage. The top rail is bent and broken in several places. The concrete base is cracked and crumbling, with several vertical rebar rods protruding from the top. The rebar is heavily rusted and appears to be in poor condition.

A concrete retaining wall is visible in the background, constructed from large, rectangular blocks. The wall is situated on a grassy slope and appears to be in good condition.

A small stream flows through the foreground, surrounded by rocks and green vegetation. The water is clear and appears to be moving quickly over the rocks.





























