



10/27/2020



10/27/2020



10/27/2020



10/27/2020

A photograph of a road surface showing a significant pothole. The pothole is roughly rectangular and filled with a lighter-colored material, possibly sand or gravel. The surrounding asphalt is dark and shows some wear. A double yellow line runs horizontally across the top of the image. The date '10/27/2020' is printed in orange text at the bottom center of the image.

10/27/2020



10/27/2020



10/27/2020



10/27/2020





10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020

BRIDGE
NO.

BC 1449 (33)
BR 58

2
0
1
7

10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020



10/27/2020