

A photograph showing a corner of a concrete structure. The concrete is light-colored with some staining. A metal plate or beam is attached to the wall, showing significant rust and peeling paint. The date 10/02/2020 is printed in orange at the bottom right.

10/02/2020