

A photograph of a road surface showing a significant longitudinal crack. A double yellow line is painted across the road. The road is bordered by a concrete curb and some vegetation. The date '09/23/2020' is printed in orange at the bottom right.

09/23/2020