





07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020





07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020







07/01/2020



07/01/2020



07/01/2020

A photograph showing a close-up of a metal structure. The structure is primarily covered in a green, possibly painted or coated, surface. There are significant areas of rust and corrosion, particularly along the edges and in a central, irregularly shaped area where the green coating has been lost, revealing a grey, metallic surface. The rust is a reddish-brown color. The overall appearance is that of an old, weathered metal component. The date "07/01/2020" is printed in orange text at the bottom center of the image.

07/01/2020



07/01/2020



07/01/2020

07/01/2020



07/01/2020



07/01/2020



07/01/2020



07/01/2020





07/01/2020





07/01/2020



07/01/2020



07/01/2020





07/01/2020