



08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020



2465

SIMON

08/25/2020



08/25/2020



08/25/2020



2465

SIMON

08/25/2020



08/25/2020



08/25/2020



08/25/2020





08/25/2020





08/25/2020





08/25/2020



08/25/2020





A photograph showing a dark, enclosed space, possibly a crawlspace or basement. The wall is made of concrete and shows significant signs of mold and water damage. The mold is green and black, and the paint is peeling and chipped away, revealing a reddish-brown surface underneath. A date stamp '08/25/2020' is visible in the bottom right corner.

08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020





08/25/2020





08/25/2020







08/25/2020



08/25/2020







08/25/2020



08/25/2020



08/25/2020



08/25/2020







08/25/2020



08/25/2020





08/25/2020



08/25/2020



08/25/2020



08/25/2020





