



08/25/2020



08/25/2020



08/25/2020





08/25/2020



08/25/2020



08/25/2020

08/25/2020



08/25/2020



08/25/2020



08/25/2020

A photograph of a concrete surface, possibly a sidewalk or driveway. A vertical, yellowish-brown stain runs down the center of the frame. At the top, there is a dark horizontal line, likely a joint or a shadow. The concrete is light gray and shows some texture and small debris. In the bottom left corner, a small portion of a yellow and black object is visible. A date stamp is located in the bottom right area of the image.

08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020



08/25/2020

BRIDGE
NO.

BRO 1442 (24)
BR 56

MOON

08/25/2020





08/25/2020



08/25/2020



08/25/2020



08/25/2020



A photograph of a concrete floor joint. A wooden strip is placed vertically across the joint. Red paint is applied to the concrete surface, primarily along the joint and the wooden strip. The floor is made of light-colored concrete tiles. The date '08/25/2020' is printed in the bottom right corner.

08/25/2020



08/25/2020



08/25/2020





08/25/2020



08/25/2020



08/25/2020





08/25/2020



08/25/2020

A photograph showing a metal guardrail on the right side of a gravel shoulder. The guardrail is made of galvanized steel and has several vertical posts. To the left of the guardrail is a grassy area with some weeds and a concrete curb. The gravel shoulder is on the right. A date stamp '08/25/2020' is visible in the bottom right corner of the image.

08/25/2020