



09/01/2020



09/01/2020



09/01/2020



09/01/2020





09/01/2020

A photograph of a paved asphalt surface, likely a driveway or walkway. The surface is dark grey and shows signs of wear, including a prominent crack running diagonally from the upper left towards the center. The area is partially covered by shadows cast by trees or bushes, creating a dappled light effect. In the foreground, there is a pile of dry, brown pine needles and some small twigs. The background shows a concrete curb and some green foliage. A date stamp is visible in the bottom right corner.

09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020





09/01/2020



09/01/2020





09/01/2020



09/01/2020





09/01/2020



09/01/2020



09/01/2020



09/01/2020



09/01/2020

09/01/2020



09/01/2020







09/01/2020



09/01/2020





09/01/2020



09/01/2020







09/01/2020