


A photograph showing a corner of a concrete structure. A horizontal metal beam, heavily rusted and dark brown, runs across the top right. The concrete on the left is light-colored and shows signs of cracking and peeling. The concrete on the right is a different shade, possibly due to moisture or staining. A small, light-colored bolt or fastener is visible on the concrete surface near the bottom left. The date '09/01/2020' is printed in orange text at the bottom center of the image.

09/01/2020