



09/15/2020



09/15/2020





09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



POSTED
WEIGHT LIMIT
24000
POUNDS

NO
TRUCKS

09/15/2020



BAKER BROOK RD
PARISH HILL TO W

NO TRUCKS

09/15/2020



09/15/2020



09/15/2020





09/15/2020













09/15/2020



09/15/2020







09/15/2020

09/15/2020



A close-up photograph of a metal roof structure showing significant rust and corrosion. The image features a corrugated metal surface on the left, a dark vertical metal beam in the center, and a textured, possibly concrete or stone, surface on the right. The metal is heavily rusted, with brown and orange spots and streaks. A date stamp '09/15/2020' is visible in the lower right corner of the image.

09/15/2020



09/15/2020



09/15/2020






09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020







09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



















