



09/15/2020



09/15/2020



09/15/2020



ONE LANE
BRIDGE

LEGAL LOAD
LIMIT
24,000
POUNDS

09/15/2020



09/15/2020



09/15/2020



09/15/2020





09/15/2020

A photograph showing a long, narrow metal leveling bar placed on a concrete surface. The bar has several circular holes spaced along its length. The concrete surface is uneven and shows signs of wear and discoloration. In the background, there is a concrete curb and some foliage. A date stamp is visible in the bottom right corner.

09/15/2020



09/15/2020



09/15/2020





09/15/2020



09/15/2020





09/15/2020





09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



TRIEBERT ROSS 302

ROCK RIVER STUDIO

09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020









09/15/2020







09/15/2020



09/15/2020



09/15/2020



09/15/2020





09/15/2020



09/15/2020



09/15/2020







09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020









09/15/2020







09/15/2020



09/15/2020



09/15/2020



09/15/2020



09/15/2020





09/15/2020



09/15/2020



09/15/2020



09/15/2020





09/15/2020



09/15/2020



09/15/2020



09/15/2020





09/15/2020



09/15/2020



09/15/2020



09/15/2020





09/15/2020



09/15/2020







































