

The image shows the underside of a wooden structure, likely a bridge or a large shed. A horizontal wooden beam, identified as the bottom chord, is fractured in the middle. The wood is weathered and greyish. To the right, there are vertical wooden studs. Above the main beam, there are green-painted metal brackets with circular holes. The background consists of horizontal wooden planks. The text 'UNDERSIDE OF FRACTURED DOWNSTREAM BOTTOM CHORD' is overlaid in yellow on the left side of the image.

UNDERSIDE OF FRACTURED DOWNSTREAM
BOTTOM CHORD