



04/25/2019



04/25/2019



04/25/2019



04/25/2019





04/25/2019



04/25/2019



04/25/2019




04/25/2019



04/25/2019



04/25/2019

A photograph showing a close-up view of a road joint. A metal strip is embedded in a concrete groove, with a visible crack running through it. The surrounding road surface is asphalt with yellow double lines. The date stamp '04/25/2019' is located in the bottom right corner of the image.

04/25/2019



04/25/2019





04/25/2019



04/25/2019



04/25/2019



04/25/2019