











A worker wearing a high-visibility orange and yellow safety vest over a light blue t-shirt and light blue jeans. The worker is standing on the bridge deck, looking towards the right side of the frame.

The structure consists of a bridge deck with wooden planks, a concrete curb, and a green-painted metal railing. A large, green-painted metal beam is bent and broken, with a section of the beam protruding from the deck. The railing has vertical bars and a top rail. The bridge is situated over a river, with dense green trees in the background.

A large, green-painted metal beam that has been bent and broken. A section of the beam is protruding from the bridge deck, showing significant damage and rust. The beam is secured with bolts and nuts.

Small green plants growing from the concrete curb and the ground near the bridge deck.

A small, round, black and green object, possibly a marker or a cap, lying on the concrete curb.





























