



STATE OF VERMONT
AGENCY OF TRANSPORTATION
MATERIALS & RESEARCH SECTION
SUBSURFACE INFORMATION

BORING LOG

WATERBURY
IM 089-2(43)
EXIT #10 NB OFF RAMP-A BR-47

Boring No.: B-102
Page No.: 1 of 1
Pin No.: 10A076
Checked By: CEE

Boring Crew: GARROW, WERNER
Date Started: 12/09/10 Date Finished: 3/18/11
VTSPG NAD83: N 671095.76 ft E 1575510.29 ft
Station: 103+37.75 Offset: -1.37
Ground Elevation: 469.58 ft

Casing Type: WB
Sampler Type: SS
I.D.: 4 in 1.5 in
Hammer Wt: N.A. 140 lb.
Hammer Fall: N.A. 30 in.
Hammer/Rod Type: Auto/AWJ
Rig: CME 45C TRACK CE = 1.34

Groundwater Observations		
Date	Depth (ft)	Notes

Depth (ft)	Strata (1)	CLASSIFICATION OF MATERIALS (Description)	Run (Dip deg.)	Core Rec. % (ROD %)	Drill Rate minutes/ft	Blows/6" (N Value)	Moisture Content %	Gravel %	Sand %	Fines %
0.0 - 0.4		Asphalt Pavement, 0.0 ft - 0.4 ft								
0.4 - 1.4		Concrete, 0.4 ft - 1.4 ft								
1.4 - 3.0		Visual Classification, 3" minus crushed rock				7-5-15-5 (20)	8.1	39.2	47.5	13.3
3.0 - 3.7		A-1-b, GrSa, brn, Moist, Rec. = 0.3 ft								
3.7 - 4.6		A-1-b, SiSaGr, gry, Wet, Rec. = 0.9 ft				7-8-11-14 (19)	10.8	54.3	25.3	20.4
4.6 - 5.8		A-1-a, SaGr, gry, Wet, Rec. = 1.2 ft, Rock Fill was within sample.				16-32-6-6 (38)	9.0	66.9	20.9	12.2
5.8 - 6.6		A-1-b, SaGr, gry, Wet, Rec. = 0.8 ft, Rock Fill was within sample.				9-5-2-6 (7)	11.8	53.4	27.7	18.9
6.6 - 8.0		A-1-a, SaGr, gry, Wet, Rec. = 1.4 ft, Lots of Rock Fill was within sample.				11-9-7-6 (16)	8.7	61.9	24.1	14.0
8.0 - 9.1		A-1-a, SaGr, gry, Wet, Rec. = 1.1 ft, Sample was mostly Rock Fill.				12-48-53-R (R)	10.0	57.2	29.0	13.8
9.1 - 10.0		A-1-a, SaGr, gry, Wet, Rec. = 0.9 ft, Sample was mostly Rock Fill.				18-15-15-13 (30)	10.0	59.1	27.7	13.2
10.0 - 10.6		A-1-b, SaGr, gry, Wet, Rec. = 0.6 ft, Sample was mostly Rock Fill.				11-13-8-12 (21)	13.7	53.0	31.4	15.6
10.6 - 11.5		A-1-a, SaGr, gry, Wet, Rec. = 0.7 ft, Sample was mostly Rock Fill.				8-9-9-14 (18)	11.8	61.4	27.1	11.5
11.5 - 12.4		A-1-b, SaGr, gry, Wet, Rec. = 0.9 ft, Sample was mostly Rock Fill.				10-10-10-6 (20)	13.8	55.1	28.3	16.6
24.8 - 25.8		24.8 ft - 25.8 ft, Light gray, Quartz-sericite-chlorite Phyllitic Schist, Moderately hard, Unweathered, Fair rock, NXMDC	1 (70)	60 (0)	16					
25.8 - 26.9		25.8 ft - 26.9 ft, Same as above. Fair rock, NXMDC	2 (70)	87 (43)	15					
26.9 - 27.4		26.9 ft - 27.4 ft, Drilling Break.			10					
27.4 - 28.8		27.4 ft - 28.8 ft, Same as top section. Fair rock			12					
28.8 - 33.8		28.8 ft - 33.8 ft, Light gray, Quartz-sericite-chlorite Phyllitic Schist, Moderately hard, Unweathered, Good rock, NXMDC	3 (70)	70 (72)	4					
33.8 - 34.8		33.8 ft - 34.8 ft, Light gray, Quartz-sericite-chlorite Phyllitic Schist, Moderately hard, Unweathered, Good rock, NXMDC	4 (70)	100 (100)	4					
34.8 - 35.0		Hole stopped @ 34.8 ft								
35.0 - 40.0		Remarks: No water table reading was taken.								

BORING LOG 2 WATERBURY IM 089-2(43).GPJ VERMONT AOT.GDT 4/13/11

Notes:
1. Stratification lines represent approximate boundary between material types. Transition may be gradual.
2. N Values have not been corrected for hammer energy. CE is the hammer energy correction factor.
3. Water level readings have been made at times and under conditions stated. Fluctuations of groundwater may occur due to other factors than those present at the time measurements were made.