



STATE OF VERMONT
 AGENCY OF TRANSPORTATION
 CONSTRUCTION AND
 MATERIALS BUREAU
 CENTRAL LABORATORY

BORING LOG

Springfield
 BF 0134(45)
 VT 11 Culv. 60

Boring No.: B-102

Page No.: 1 of 1

Pin No.: 13d336

Checked By: END

Boring Crew: Emerson, Judkins, Gomes

Date Started: 7/28/16 Date Finished: 7/28/16

VTSPG NAD83: N 291171.15 ft E 1641329.99 ft

Station: 364+56 Offset: 23.22

Ground Elevation: 491.7 ft

Type:	Casing	Sampler
I.D.:	WB	SS
Hammer Wt:	4 in	1.5 in
Hammer Fall:	N.A.	140 lb.
Hammer/Rod Type:	N.A.	30 in.
Rig:	Auto/AWJ	
	CME 45C SKID SUB>><<SUB>>	= 1.42

Groundwater Observations

Date	Depth (ft)	Notes
07/28/16		No W.T. observed

Depth (ft)	Strata (1)	CLASSIFICATION OF MATERIALS (Description)	Blows/6" (N Value)	Moisture Content %	Gravel %	Sand %	Fines %
		Asphalt Pavement, 0.0 ft - 0.45 ft					
2.5		A-1-b, GrSa, brn, Moist, Rec. = 1.3 ft	4-3-3-3 (6)	9.2	40.0	46.8	13.2
		A-2-4, SiGrSa, brn, Moist, Rec. = 1.1 ft	4-6-22-14 (28)	11.0	30.4	46.5	23.1
		Field Note:, Rollercone, Cleaned out casing					
5.0		Field Note:, No Recovery	R@3.5" (R)				
		Hole stopped @ 5.3 ft					
7.5		Remarks: Hole collapsed at 2.5 feet. 1.) Hit culvert at 5.3 feet. Aborted drilling operations.					

Notes: 1. Stratification lines represent approximate boundary between material types. Transition may be gradual.
 <<SUB>><<SUB>> is the hammer energy correction factor.
 3. Water level readings have been made at times and under conditions stated. Fluctuations may occur due to other factors than those present at the time measurements were made.

BORING LOG 2 SPRINGFIELD BF 0134(45).GFG VERMONT AOTI.GDT 9/9/16