STATE OF VERMONT
AGENCY OF TRANSPORTATION
MATERIALS & RESEARCH DIVISION
SUBSURFACE INFORMATION

HOLE NO.: B-1
SHEET 1 OF 1
DATE STARTED: 9/13/99
DATE COMPLETED: 9/14/99

PROJECT NAME: LYNDON
SITE NAME: BR-8
STATION: 3+546.00
GROUND EL.: 228.500

PROJECT NUMBER: BRS 0269 (8)S
SITE NO.: VT-14
OFFSET: 5.00
G.W. DEPTH:

BORING CREW
CREW CHIEF: YOUNG
DRILLER: TALLMAN
LOGGER: RUSSELL
ADDITIONAL CREW:

BORING RIG: SKID RIG
BORING TYPE: WASH BORE
SAMPLE TYPE: SPLIT BARREL

DEPTH	SYMBOL	CLASSIFICATION OF MATERIALS (Description)	BLOWS PER 0.3 m	M.C. %	GRAVEL %	SAND %	FINES %	LL	PI
		A-1-a, SaGr, brn, Moist, Rec. = 0.10m	6	10.3	66.9	29.8	3.3		
		No Rec., Stone in sampler.	12						
		No sample, Boulder							
5		No sample, Boulder							
		Top of bedrock @ 6.40m							
		Run #1: BXDC, 6.40m-7.15m, Rec. = 0.42m, See Geologist's Report.	RUN 1	REC% 56	RQD% 33	Dip° 50			
		Run #2: BXDC, 7.15m-7.90m, Rec. = 0.68m, See Geologist's Report.	2	91	80	50			
		Run #3: BXDC, 7.90m-9.40m, Rec. = 1.50m, See Geologist's Report.	3	100	78	50			
10				Hole stopped @ 9.40m					

GEOLOGISTS REPORT:

Run #1: Gray quartzose limestone, Hard, Unweathered, Competent.

Run #2: Same as Run #1, Competent.

Run #3: Same as Run #1, But thin schist layering from 8.40m - 8.65m, Competent.