STATE OF VERMONT
AGENCY OF TRANSPORTATION
MATERIALS & RESEARCH DIVISION
SUBSURFACE INFORMATION

HOLE NO.: B-5
SHEET 1 OF 1
DATE STARTED: 8/10/0
DATE COMPLETED: 8/10/0

PROJECT NAME: GRANVILLE
SITE NAME: BR 15
STATION: 1+031.50
GROUND EL.: 253.421

PROJECT NUMBER: BRO 1444(34)
SITE NO.: TH 23
OFFSET: 0.00
G.W. DEPTH:

BORING CREW
CREW CHIEF: R. YOUNG
DRILLER: R. YOUNG
LOGGER: E. CHABOT
ADDITIONAL CREW:

BORING RIG: UNI-MOG
BORING TYPE: WASH BORE
SAMPLE TYPE: SPLIT BARREL

DEPTH	SYMBOL	CLASSIFICATION OF MATERIALS *(Description)*	BLOWS PER 0.3 m	M.C. %	GRAVEL %	SAND %	FINES %	LL	PI
		1.50m-2.10m, Possible fill material							
		A-1-a,SaGr,brn,Moist,rec.=0.46m	43	10.1	55.5	30.1	14.4		
				Top of Bedrock at 4.88m					
5				RUN	REC%	RQD%	DIP°		
		RUN#1: BXDC 4.88m-5.88m Rec.=0.69m		1	69	65	85		
		RUN#2: BXDC 5.88m-7.08m Rec.=1.20m See Geologist's Report		2	100	63	85		
		RUN#3: BXDC 7.08m-7.98m Rec.=0.93m See Geol. Report		3	100	100	85		
				Hole stopped at 7.98m					
10									

GEOLOGISTS REPORT:

Run #1: Pale green quartz-chlorite-albite-seracite schist with quartz veins. Moderately hard. Unweatherd. Competent.

Run #2: Same as Run #1, but rock becomes soft and moderately weathered near bottom of run.

Run #3: Same as Run #1. Competent.