








MS # 576



JERICO RD


- PEDESTAL POST
- PEDESTRIAN SIGNAL
- VIDEO CAMERA
- CONTROL BOX
- VIDEO DETECTION

US 2 WEST



US 2 EAST

BRIDGE ST



NOT TO SCALE