



MS # 585

2

5

VT 116 NORTH



FARMALL DRIVE

8

8

1 D

6

6

4

4

5

2

2

2

5 D

1

6

6

COMMERCE STREET

- ⊙ PEDESTAL POST
- ⊙→ PEDESTRIAN SIGNAL
- ⌞ PREEMPTION DETECTOR
- ♀ PREEMPTION STROBE
- ⌞ L.E.D REGULATORY SIGN
- ∟ VIDEO CAMERA
- ⊠ CONTROL BOX
- MAST ARM
- ≡ COORDINATION
- - - LOOP DETECTION
- ▭ VIDEO DETECTION
- ⊠ JB JUNCTION BOX
- ⌞ LUMINAIRE
- STANCHION

VT 116 SOUTH

NOT TO SCALE